

MONROE BROTHERS PAINT & BODY **SHOP INC**

Workfile ID: Federal ID: Resale Number:

73cfa067 38-3931914 32054804458

1480 US HWY 59 N, CARTHAGE, TX 75633

Phone: (903) 693-7465 FAX: (903) 693-5174

Preliminary Estimate

Customer: Panola County Road and Bridge Precint 4

Insured:

Panola County Road and

Bridge Precint 4

Type of Loss: Point of Impact: Date of Loss:

Policy #:

Claim #:

Days to Repair: 0

Insurance Company:

Owner:

Panola County Road and Bridge Precint 4

1121 E Sabine Carthage, TX 75633 (903) 263-1267 Business Inspection Location:

MONROE BROTHERS PAINT & BODY

SHOP INC

1480 US HWY 59 N CARTHAGE, TX 75633

Repair Facility

(903) 693-7465 Business

VEHICLE

2017 RAM 3500 Cab & Chassis Tradesman Regular Cab & Chassis 143" WB 60" 4WD 2D P/U 6-6.7L Turbocharged Diesel Diesel Direct Injection

VIN:

3C7WRLFL1GG256689

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color:

Mileage Out:

Job #:

State:

Production Date:

Condition:

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering

Power Brakes

DECOR

Dual Mirrors

Tinted Glass

Console/Storage CONVENIENCE Air Conditioning

Intermittent Wipers

Tilt Wheel

Cruise Control

Message Center

RADIO

AM Radio

FM Radio

Stereo

Search/Seek Auxiliary Audio Connection SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes Traction Control

Stability Control

Front Side Impact Air Bags

Positraction

SEATS

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

California Emissions

TRUCK

Dual Rear Wheels

Customer: Panola County Road and Bridge Precint 4

2017 RAM 3500 Cab & Chassis Tradesman Regular Cab & Chassis 143" WB 60" 4WD 2D P/U 6-6.7L Turbocharged Diesel Diesel Direct Injection

ne		Oper	Description	Part Number	Qty	Extended Price \$	Labor 	Pain
1	FENDER							_
2		Repl	RT Fender	68054338AI	1	347.00	2.0	2.
- 3 \		•	Add for Edging					0.
4			Add for Clear Coat					0
5		Repl	RT Fender liner	68148310AD	1	126.00	Ind.	
6		Repl	Nameplate "Cummins 6.7 LITER"	68149701AB	1	41.70	0.2	
7		Repl	RT Wheel flare black	1FV90RXFAF	1	209.00	0.5	
8		Repl	RT Protector	5182362AB	1	34.50	0.2	
9			LT Protector	5182363AB	1	34.85	0.2	_
10		Repl	LT Side rail	68095951AH	1	249. 00 s	4.0 S	1
11		Repl	Nameplate "Cummins 6.7 LITER"	68149701AB	1	41.70	0.2	
12		Repi	LT Front reinf	55372839AD	1	20.25		
13		Repi	RT Front reinf	55372838AD	1	20.25		
13 14		Repl		68054339AI	1	347.00	1.8	2
		Кері	Overlap Major Adj. Panel					-(
15			Add for Edging					(
16			Add for Clear Coat					(
17		Dani	· ·	68148311AC	1	127.00	Ind.	
18		Repi	Li reiter inte	•===				
19	CAB	Diad.	Cowl panel Lt					(
20	#	Bind		55112305AD	1	257.00	0.6	
21		Repl	Cowl grille RT Uniside panel hinge pillar	68145096AA	1	349.00 s	7.5	;
22		Sect		952 1200 as 0.				-
23			Overlap Major Adj. Panel					
24	INSTRUMEN						5.0	
25		R&I	R&I instrument panel					
26	HOOD		PET I Comp	5160344AC	1	67.35	0.3	
27		Repl	RT Hinge	52000.170	_			-
28			Overlap Minor Panel	55372244AK	1	625.00	1.6	
29		Repl			-			
			Note: No CAPA available.					-
30			Overlap Major Adj. Panel					
31			Add for Underside(Complete)					
32			Add for Clear Coat	E1603AEAF	1	66.20	0.3	
33		Repi	LT Hinge	5160345AC	-	00.20		
34			Overlap Minor Panel					
35	RADIATOR			6000000014	1	82.95	0.7	
36		Repl	LT H'lamp mounting	68222829AA	1	180.00	0.1	
37		Repl		68222827AB	1	5.45	V	
38		Repl		68222836AA		5.45		
39		Repl		68222836AA	1	82.95	0.7	
40		Repl	•	68222828AA	1	180.00	0.1	
41		Repl	RT Hilamp bracket	68222826AB	1	100.00	V.2	

Customer: Panola County Road and Bridge Precint 4

2017 RAM 3500 Cab & Chassis Tradesman Regular Cab & Chassis 143" W8 60" 4WD 2D P/U 6-6.7L Turbocharged Diesel Diesel Direct Injection

2017 RAI	M 3500 Cab & Ch	assis Tr	adesman Regular Cab & Chassis 143" W	'B 60° 4WD 2D P/U 6-6.7	L Turboci	narged Diese Dies	ei Direct Tiljection	
43		Repl	RT Headiamp assy w/o projector chrome	68096438AJ	1	210.00	0.6	
			Note: No CAPA avbailable.					
44			Aim headlamps				0.5	
45		Repl	LT Headlamp assy w/o projector	6809 64 39AG	1	219.00	0.6	
13			chrome					
46	FRONT BUMPE	R					26	
47			O/H front bumper			437.00	2.6 Incl.	1.8
48	**	Repl	RECOND Bumper paintable w/o park snsr	1MQ02TZZAB	1	637.00	iua.	
49			Add for Clear Coat					0.7
50		Repl	RT Support bracket	68064329AD	1	51.35	Ind.	
51		Repl	LT Support bracket	68064329AD	1	51.35	Ind.	
52	*	Repl	RT Mount bracket tow hook bracket & tow hook	68196252AB	1	<u>395.00</u>	0.3	
53	*	Repi	LT Mount bracket tow hook bracket & tow hook	68196253AB	1	<u>395.00</u>	0.3	
54		Reni	LT Side bracket	68064309AA	1	51.35		
55		Repl		68064309AA	1	51.35		
56	#	Repl	Bumper flare ext Rt		1	142.00		
57	#	Repl	Bumper flare ext Lt		1	142.00		
58	WINDSHIELD	•						
59	***************************************	Repl	Windshield NAGS, w/o OEM logo, w/humldity snsr w/rain sensor	DW02098GTY	1	486.80	2.9	
60		Repl	RT Side molding	68297608AA	1	92.85	Ind.	
61	#	Rpr	Set up & measure				1.5	
62	#	Rpr	Pull to square A-Pillar Rt				1.5 F	
63	FRONT DOOR	-	·					
64	100111	Repl	RT Outer panel crew & mega cab	68224644AB	1	345.00	6.8	2.8
65			Overlap Major Adj. Panel					-0.4
66			Add for Edging					0.5
67			Add for Clear Coat					0.1
68			Add for Inside					0.5
69			Add for Clear Coat					0.1
70			Clear Coat					2.5
71	*	Rpr	RT Door shell crew & mega ćab				1.0	Ind.
72		Repl		6814035DAC	1	82.45	0.2	
73		R&I					0.5	
74		Repi	RT Mirror assy	68412768AA	1	189.00	Incl.	
7. 75	#	-	TINT COLOR					0.5
76	#	Rpr					0.8	
70 77	#	Subi			1	10.00 X		
778	#	Repl			1	5.00		
70 79	#	Repl			1	10.00	0.3	
80	#	Repl			1	10.00	0.3	
81	#	Ror					0.3	
01	π-	.4						

Customer: Panola County Road and Bridge Precint 4

2017 RAM 3500 Cab & Chassis Tradesman Regular Cab & Chassis 143" WB 60" 4WD 2D P/U 6-6.7L Turbocharged Diesel Diesel Direct Injection

	#	SUBTOTALS 7,079		7,079.10	47.0	23.1
83	#	E.P.C.	1	3.00		
92		OTHER CHARGES				

ESTIMATE TOTALS	Basis		Rate	Cost \$
Category				7,066.10
Parts	41.5 hrs	@	\$ 60.00 /hr	2,490.00
Body Labor	23.1 hrs	@	\$ 60.00 /hr	1,386.00
Paint Labor	1.5 hrs	@	\$ 85.00 /hr	127.50
Frame Labor	4.0 hrs	@	\$ 85.00 /hr	340.00
Structural Labor	23.3 hrs	@	\$ 42.00 /hr	978.60
Paint Supplies	23.3 1113	6	4 .2.00 /	10.00
Miscellaneous				3.00
Other Charges				
Subtotal				12,401.20
Sales Tax	\$ 8,047.70	@	6.2500 %	502.98
Grand Total				12,904.18
Deductible				0.00
CUSTOMER PAY				0.00
INSURANCE PAY				12,904.18

Customer: Panola County Road and Bridge Precint 4

2017 RAM 3500 Cab & Chassis Tradesman Regular Cab & Chassis 143" WB 60" 4WD 2D P/U 6-6.7L Turbocharged Diesel Diesel Direct Injection

Estimate based on MOTOR CRASH ESTIMATING GUIDE and potentially other third party sources of data. Unless otherwise noted, (a) all items are derived from the Guide DR3TH13, CCC Data Date 7/17/2018, and potentially other third party sources of data; and (b) the parts presented are OEM-parts manufactured by the vehicles Original Equipment Manufacturer. OEM parts are available at OE/Vehicle dealerships. OPT OEM (Optional OEM) or ALT OEM (Alternative OEM) parts are OEM parts that may be provided by or through alternate sources other than the OEM vehicle dealerships. OPT OEM or ALT OEM parts may reflect some specific, special, or unique pricing or discount. OPT OEM or ALT OEM parts may include "Blemished" parts provided by OEM's through OEM vehicle dealerships. Asterisk (*) or Double Asterisk (**) indicates that the parts and/or labor data provided by third party sources of data may have been modified or may have come from an alternate data source. Tilde sign (~) items indicate MOTOR Not-Included Labor operations. The symbol (<>) Indicates the refinish operation WILL NOT be performed as a separate procedure from the other panels in the estimate. Non-Original Equipment Manufacturer aftermarket parts are described as Non OEM, A/M or NAGS. Used parts are described as LKQ, RCY, or USED. Reconditioned parts are described as Recond. Recored parts are described as Recore. NAGS Part Numbers and Benchmark Prices are provided by National Auto Glass Specifications. Labor operation times listed on the line with the NAGS information are MOTOR suggested labor operation times. NAGS labor operation times are not included. Pound sign (#) Items Indicate manual entries.

Some 2019 vehicles contain minor changes from the previous year. For those vehicles, prior to receiving updated data from the vehicle manufacturer, labor and parts data from the previous year may be used. The CCC ONE estimator has a list of applicable vehicles. Parts numbers and prices should be confirmed with the local dealership.

The following is a list of additional abbreviations or symbols that may be used to describe work to be done or parts to be repaired or replaced:

SYMBOLS FOLLOWING PART PRICE:

m=MOTOR Mechanical component. s=MOTOR Structural component. T=Miscellaneous Taxed charge category. X=Miscellaneous Non-Taxed charge category.

SYMBOLS FOLLOWING LABOR:

D=Diagnostic labor category. E=Electrical labor category. F=Frame labor category. G=Glass labor category. M=Mechanical labor category. S=Structural labor category. (numbers) 1 through 4=User Defined Labor Categories.

OTHER SYMBOLS AND ABBREVIATIONS:

Adj.=Adjacent. Algn.=Align. ALU=Aluminum. A/M=Aftermarket part. Blnd=Blend. BOR=Boron steel. CAPA=Certified Automotive Parts Association. D&R=Disconnect and Reconnect. HSS=High Strength Steel. HYD=Hydroformed Steel. Incl.=Included. LKQ=Like Kind and Quality. LT=Left. MAG=Magnesium. Non-Adj.=Non Adjacent. NSF=NSF International Certified Part. O/H=Overhaul. Qty=Quantity. Refn=Refinish. Repl=Replace. R&I=Remove and Install. R&R=Remove and Replace. Rpr=Repair. RT=Right. SAS=Sandwiched Steel. Sect=Section. Subl=Sublet. UHS=Ultra High Strength Steel. N=Note(s) associated with the estimate line.

CCC ONE Estimating - A product of CCC Information Services Inc.

The following is a list of abbreviations that may be used in CCC ONE Estimating that are not part of the MOTOR CRASH ESTIMATING GUIDE:

BAR=Bureau of Automotive Repair. EPA=Environmental Protection Agency. NHTSA= National Highway Transportation and Safety Administration. PDR=Paintless Dent Repair. VIN=Vehicle Identification Number.

Customer: Panola County Road and Bridge Precint 4

2017 RAM 3500 Cab & Chassis Tradesman Regular Cab & Chassis 143" WB 60° 4WD 2D P/U 6-6.7L Turbocharged Diesel Diesel Direct Injection

PARTS SUPPLIER LIST

Line	Supplier	Description	Price
48	Keystone - P+ A-Whitehouse	#CH1002392R	\$ 637.00
70	13681 SYDNEY ROAD WHITEHOUSE TX 75791 (866) 837-0051	RECOND Bumper paintable w/o park snsr	
	(903) 592-7455		



Condition Report

Date: 8/5/2018 **Property Condition: Repairable**

Assignment Number 900-808-0016

Loss Recap for Repairable

Damage Appraisal..\$11,571.83 Percent of ACV...... 0.00% Deductible.....\$1,000.00 Total......\$10,571.83 Approximate ACV...\$0.00

Office:

PDATyler, TX #900 3318 SSW Loop 323 Suite B

Tyler, TX 75701 Phone: 903-581-6000 Fax: 903-581-8637

Insurance Company:

TRAVELERS INSURANCE Adjuster: Shardea Miller

Date of Loss: 7/31/2018 Assignment Received: 8/3/2018

Date of First Contact: 8/3/2018

Date of Inspection: 8/3/2018

Inspection Location: **COUNTY PIT CARTHAGE, TX 75633**

Vehicle/Owner Information:

Insured: Panola County Vehicle: 2016 Dodge 4500 VIN #: 3C7WRLFL1GG256689 **Repair Facility:**

MONROE BROTHERS

1480 HWY 59 N CARTHAGE, TX 75633

Fax: (903) 693-5174

Loss Recap

Estimated Amount of Open Damages: \$0.00

Estimated Salvage Value: \$0.00

Repair Facility Estimate Amount: \$0.00

Recommendation: Repairable

Primary Damage: Left Front Corner Secondary Damage: Right Front Corner

Damage Appraisal: \$11,571.83

Claim #: FAZ5133

Policy #:

Agreed Scope of Damage: No

Days to Repair: 18

Appearance Allowance: No

Betterment/Depreciation: No

Applicable: Reason:

Tow Charges: \$0.00

Storage Rate Per Day / Total: N/A

Direction to Pay: Unknown

Drivable: No

Condition Summary

Interior: Average

Paint: Average

Mileage: 46965

Special Equipment:

Approx Cost of Special Equipment: \$0.00

Tire Information:

Tread Depth:

LF:0 RF: 0 LR:0 RR: 0

Spare:0

Size: Type:

Remarks The vehicle was inspected at the owners work location. The owner was present at the time of inspection. Per photos the damage is to the front end of the truck.

The bumper, grille, hood, headlights, fenders, left fender support, left radiator support, right door, mirror, windshield, windshield pillar, cowl grille are damaged.

The right front tire appears to be leaning in. I have allowed a front end alignment to have it checked. Copy of appraisal not provided to anyone

Open Items

Date: 8/ 5/2018 09:31 PM

Page 1 of 5

Estimate ID: 9008080016

Estimate Version: 0

Committed Profile ID: * PDA TX

Property Damage Appraisers (PDA Tyler)

3318 SSW Loop 323 Ste B, Tyler, TX 75701 (903) 581-6000 Fax: (903) 581-8637 Email: pdatyler@pdaorg.net

Not An Authorization For repair
Read disclaimers following appraisal calculations.

Damage Assessed By: MARK DUKE Classification:

Appraised For: Shardea Miller

Condition Code: Good

Type of Loss: Collision

Date of Loss: 7/31/2018 Contact Date: 8/ 3/2018

ontact Date: 8/ 3/2018

Deductible: 1,000.00

File Number: 9008080016

Date Assigned: 8/ 3/2018

File Number: 9008080016 Claim Number: FAZ5133

Insured: Panola County
Owner: Panola County

Mitchell Service: 911349

Description: 2016 Dodge RAM HD Chassis Cab

Vehicle Production Date: 1/16

Type/Component: Truck

Software Version:

7.1.229

Drive Train:

VIN: 3C7WRLFL1GG256689

License: 1289255 TX

Mileage: 46,965

OEM/ALT: A

Parts Profile Version: 4

Parts Profile: Tyler Color: WHITE

Line Item	Entry Number	Labor Type	Operation	Line Item Description	Part Type/ Part Number	Dollar Amount	Labor Units
1	933037	FRM	ADD'L OPR	Frame/Unibody Repair And Setup	T dit italiaci	3.00 *	
2	101479	REF	REFINISH	Frt Bumper Cover		C	
3	101481	BDY	OVERHAUL	Frt Bumper Assy		•	2.2 #
4	101749	BDY	REMOVE/REPLACE	Frt Bumper	1MQ03RXFAB	580.00	INC*#
5	103611	BDY	REMOVE/REPLACE	R Frt Bumper End Cover	^^OE SURPLUS	52.87	0.2 #
6	103612	BDY	REMOVE/REPLACE	L Frt Bumper End Cover	^^OE SURPLUS	48.35	0.2 #
7	103464	BDY	REMOVE/REPLACE	Frt Bumper Moulding Insert	** QUAL REPL PART	59.00	INC*#
8	102709	BDY	REMOVE/REPLACE	Frt Bumper Air Dam	New	114.00	INC*
9	101156	BDY	REMOVE/REPLACE	Frt Bumper Bracket	^^OE SURPLUS	44.72	
10	101157	BDY	REMOVE/REPLACE	Frt Bumper Support	^^OE SURPLUS	46.08	
11	101158	BDY	REMOVE/REPLACE	Frt Fog Lamp Mounting Kit	** QUAL REPL PART	33.00	#
12	102714	BDY	REMOVE/REPLACE	Grille	** QRP Certified	449.00	0.5 #
13	102571	BDY	REMOVE/REPLACE	Grille Plate	68140322AA	41.70	0.2
14	103478	BDY	REMOVE/REPLACE	R Frt Combination Lamp	** QUAL REPL PART	185.00	0.7 #
15	103479	BDY	REMOVE/REPLACE	L Frt Combination Lamp	** QRP Certified	193.00	0.7 #
16	101059	REF	REFINISH	Hood Outside		C	3.2
17	101060	REF	REFINISH	Add For Hood Underside		C	1.6
18	101061	REF	REFINISH	R Hinge		C	0.5
19	101062	REF	REFINISH	L Hinge		C	0.5
20	101461	BDY	REMOVE/INSTALL	R Hood Washer Nozzle			0.2 #
21	101462	BDY	REMOVE/INSTALL	L. Hood Washer Nozzle			0.2 #
22	101064	BDY	REMOVE/REPLACE	Hood Panel	" ** QUAL REPL PART	462.00	1.3
23	101068	BDY	REMOVE/REPLACE	R Hood Hinge	^^OE SURPLUS	55.53	0.2 #
24	101069	BDY	REMOVE/REPLACE	L Hood Hinge	^^OE SURPLUS	54.51	0.2 #
25	103137	REF	REFINISH	L Side Rail			1.0
26	103168	BDY	REMOVE/REPLACE	L Cooling Bracket	** QUAL REPL PART	62.00	0.7 #
27	102988	BDY	REMOVE/REPLACE	L Cooling Headlamp Bracket	** QUAL REPL PART	106.00	0.3
			JMBER: 08/05/2018 21:3 OEM: JUL 18 V0803	1:05 9008080016 Alternate Parts: 08/05/2018 20:49:06			

Copyright (C) 1994 - 2018 Mitchell International

All Rights Reserved

Date: 8/ 5/2018 09:31 PM

9008080016

Estimate ID: 90
Estimate Version: 0

Committed Profile ID: * PDA TX

						PDA IX
28	102994	BDY	REMOVE/REPLACE	L Cooling Side Rail	^^OE SURPLUS	224.00 4.5 #
29	101102	REF	REFINISH	R Fender Outside		C 2.2
30	101103	REF	REFINISH	L Fender Outside		C 2.2
31	101104	REF	REFINISH	R Add To Edge Fender		C 0.5
32	101105	REF	REFINISH	L Add To Edge Fender		C 0.5
33	101111	BDY	REMOVE/REPLACE	R Fender Panel	** QRP Certified	305.00 3.2 #
34	101112	BDY	REMOVE/REPLACE	L Fender Panel	** QRP Certified	305.00 3.2 #
35	101113	BDY	REMOVE/REPLACE	R Fender Reinforcement	^^OE SURPLUS	14.50 0.1
36	101114	BDY	REMOVE/REPLACE	L Fender Reinforcement	^^OE SURPLUS	16.59 0.1
37	101115	BDY	REMOVE/REPLACE	R Fender Liner	68053738AI	113.00 0.3
38	101116	BDY	REMOVE/REPLACE	L Fender Liner	68053739AI	113.00 0.3
39	100171	BDY	REMOVE/REPLACE	R Frt Fender Wheel Opening Midg	^^OE SURPLUS	136.00 0.2
40	100171	BDY	REMOVE/REPLACE	L Frt Fender Wheel Opening Midg	^^OE SURPLUS	136,00 0.2
41	100049	BDY	REMOVE/REPLACE	R Rear Fender Wheel Opening Midg	^^OE SURPLUS	141.00 0.4
42	100043	BDY	REMOVE/REPLACE	L Rear Fender Wheel Opening Midg	1KA01RXFAD	149.00 0.4
43	102496	BDY	REMOVE/REPLACE	R Fender Adhesive Nameplate	^^OE SURPLUS	25,17 0,2
44	102497	BDY	REMOVE/REPLACE	L Fender Adhesive Nameplate	^^OE SURPLUS	25.17 0.2
45	100055	BDY	REMOVE/INSTALL	Fender Antenna Mast	Existing	0.1*
46	103354	GLS	REMOVE/REPLACE	W/Shield Glass	Sublet	583.99 * 0.0*#
47	100247	MCH	REMOVE/INSTALL	Instrument Panel Assy -M	Subjet	5.2 #
48	100247	REF	REFINISH	R Cab Hinge Pillar		C 1.0
		REF	BLEND	R Roof Rail	1	C 0.6 #
49 50	100455	BDY	REMOVE/REPLACE			9.6
	100457			R Section Cab Hinge Pillar	^^OE SURPLUS	234.00 0.5 #
51	100498	BDY	REMOVE/REPLACE	Cab Cowl Top Panel		234.00 0.5 #
52	102296	BDY	REMOVE/INSTALL	L Cab Side Panel	Existing ^^OE SURPLUS	
53	103623	BDY	REMOVE/REPLACE	R Otr Cab Door Opening Panel -S	""UE SURPLUS	337.00 INC* C 2.8
54	100373	REF	REFINISH	R Frt Door Outside		
55	100374	REF	BLEND	L Frt Door Outside		C 1.1
56	100381	REF	REFINISH	R Frt Add For Jambs		C 0.5
57	931104	MCH	REMOVE/REPLACE	Front End Alignment	Sublet	69.95 * 0.0*
58	101387	BDY	REPAIR	R Frt Door Shell	Existing	1.0*#
59	101389	BDY	REMOVE/REPLACE	R Frt Door Repair Panel	^^OE SURPLUS	281.00 7.2 #
6Ò	101194	BDY	REMOVE/INSTALL	L Frt Door Mirror		0.7 #
61	103256	BDY	REMOVE/REPLACE	R Frt Door Mirror Assy	** QUAL REPL PART	439.00 0.3 #
62	100469	BDY	REMOVE/INSTALL	R Frt Otr Door Belt Moulding ,		0.2
63	100470	BDY	REMOVE/INSTALL	L Frt Otr Door Belt Moulding		0.2
64	102397	BDY	REMOVE/REPLACE	R Frt Door Adhesive Nameplate	68139450AC	79.85 0.2
65	102398	BDY	REMOVE/REPLACE	L Frt Door Adhesive Nameplate	68139450AC	79.85 0.2
66	101206	BDY	REMOVE/INSTALL	R Frt Door Trim Panel		0.4
67	101207	BDY	REMOVE/INSTALL	L Frt Door Trim Panel		0.4
68	101144	BDY	REMOVE/INSTALL	R Frt Door Glass Run	Existing	0.2*
69	101145	BDY	REMOVE/INSTALL	L Frt Door Glass Run	Existing	0.2*
70	936012		ADD'L COST	Hazardous Waste Disposal		3.00 *
71	933002	REF	ADD'L OPR	Clear Coat		2.5*
72	900500	BDY *	REMOVE/REPLACE	County Decals	Sublet	150.00 * 0.0*
73	900500	MCH*	ADD'L LABOR OP	Check Brake Burning Smell	Existing	1.0*
74	AUTO		ADD'L COST	Paint/Materials		450.00 *

^{* -} Judgment Item

^{# -} Labor Note Applies
** QRP Certified - Quality Replacement Parts - Certified
** QUAL REPL PART - Quality Replacement Parts

C - Included in Clear Coat Calc

Date: 8/ 5/2018 09:31 PM
Estimate ID: 9008080016
Estimate Version: 0

Committed

Profile ID: * PDA TX

BODY PANELS OF MEMPHIS 2282 WHITTEN RD. MEMPHIS TN 38133 (800) 530-7744		KEYSTONE-INS QUALITY PRT 307 DEPORT DR. WACO TX 76712 (866) 247-5165 (254) 751-1559		KINSEL PARTS CENTER OEMD 3355 EASTEX FWY BEAUMONT TX 77706 (800) 323-4090	
11 ** D5960 26 ** D7181 27 ** D8049	33.00 62.00 106.00	22 ** CH1230307	462.00	5	52.87 48.35 44.72 46.08 55.53 54.51 224.00 14.50 16.59 136.00 136.00 141.00 25.17 234.00 337.00 281.00
KEYSTONE HIG KEYSIQ 13681 SYDNEY RD. WHITEHOUSE TX 75791 (866) 837-0051 (903) 592-7455		KEYSTONE HIG KEYSIQ 307 DEPORT DR. WACO TX 76712 (866) 247-5165 (254) 751-1559		KEYSTONE KEYSIQ 13681 SYDNEY RD. WHITEHOUSE TX 75791 (866) 837-0051 (903) 592-7455	
14 ** CH2503242N 15 ** CH2502242N 33 ** CH1241259C 34 ** CH1240269PP KEYSTONE KEYSIQ 307 DEPORT DR. WACO TX 76712 (866) 247-5165 (254) 751-1559	185.00 193.00 305.00 305.00	7 ** CH1037103C	59.00	12 ** CH1200373C	449.00
61 ** CH1321350	439.00				

Estimate Totals

ı.	Labor Subtotals	Units	Rate	Add'i Labor Amount	Sublet Amount	Totals	11.		Amount
	Body	44.5	60.00	0.00	0.00	2,670.00 T		Taxable Parts	5,740.89
	Refinish	22.9	60.00	0.00	0.00	1,374.00 T		Man Wannella Banda	200.04
	Frame	0.0	70.00	3.00	0.00	3.00 T		Non-Taxable Parts	803.94
	Mechanical	6.2	85.00	0.00	0.00	527.00 T		T-4-1 D14 D4- A4	0.544.00
		Taxable L	abor.			4,574.00		Total Replacement Parts Amount	6,544.83
	Labor Summary	73.6				4,574.00			
III.	Additional Costs					Amount	īV.	Adjustments	Amount
	Taxable Cost	S				450.00		Insurance Deductible	1,000.00-
	Non-Taxable Costs					3.00		Customer Responsibility	1,000.00-
	Total Additional Costs					453.00			
	Paint Material	Method: Ra	ates						

Init Rate = 42.00 , Init Max Hours = 99.9, Add! Rate = 0.00

ESTIMATE RECALL NUMBER: 08/05/2018 21:31:05 9008080016
Mitchell Data Version: OEM: JUL_18_V0803 Alternate I Alternate Parts: 08/05/2018 20:49:06

Software Version:

7.1.229

Copyright (C) 1994 - 2018 Mitchell International All Rights Reserved

Date: 8/ 5/2018 09:31 PM 9008080016 Estimate ID:

Estimate Version: 0 Committed

Profile ID: * PDA TX

4.574.00 Total Labor: 6,544.83 Total Replacement Parts: 453.00 **Total Additional Costs: Gross Total:** 11,571.83

1.000.00-IV. Total Adjustments: 10,571.83 Net Total:

THIS ESTIMATE HAS BEEN PREPARED BASED ON THE USE OF REPLACEMENT PARTS SUPPLIED BY A SOURCE OTHER THAN THE MANUFACTURER OF YOUR MOTOR VEHICLE. WARRANTIES APPLICABLE TO THESE REPLACEMENT PARTS ARE PROVIDED BY THE MANUFACTURER OR DISTRIBUTOR OF THESE PARTS RATHER THAN THE MANUFACTURER OF YOUR VEHICLE.

Point(s) of Impact

1 Right Front Corner (P), 11 Left Front Corner (S)

Insurance Co: TRAVELERS INSURANCE

DENVER, CO 00000

Work Phone: (303) 740-1865

Inspection Site: COUNTY PIT

CARTHAGE, TX 75633

Inspection Date: 8/ 3/2018

Body Shop: MONROE BROTHERS Address: 1480 HWY 59 N CARTHAGE, TX 75633 Telephone: (903) 693-7465

Fax Phone: (903) 693-5174 TIN: 38-3931914

Email: monroesbodyshop@aol.com

This is not an authorization for repair. All costs of repairs are the sole responsibility of the vehicle owner, who must authorize all repairs. Failure to deliver a copy of this appraisal to the repair shop by the vehicle owner may result in out of pocket expense to the vehicle owner. Providing a copy of this appraisal is not an acceptance of coverage or liability and all issues of coverage or liability are to be determined by the insurance carrier.

Deductibles may or may not be addressed or included in this appraisal. If applicable, the repairer should collect the deductible from the vehicle owner prior to the release of the repaired vehicle. It is the repairer's responsibility to send notification of the

supplement via fax or email to PDA, including a statement whether the repairs have been halted on the vehicle. PDA will respond to your request within 24 hours. Please allow 48 hours to complete supplement processing from the date of request to ensure timely release of the vehicle.

This appraisal is subject to the complete review and approval by the

Date: 8/ 5/2018 09:31 PM Estimate ID: 9008080016

Estimate Version: 0

Committed Profile ID: * PDA TX

assigning insurance company to assure accuracy, cost effectiveness, and that accepted industry repair standards are met. The insurance company listed has the right to accept or reject any part or all of this appraisal or make any changes they feel necessary.